


Figure 23
Auditorium, close up of dome panel-
ing with junction of auditorium
lobby with amphitheater.



Auditorium, lobby entrance.

Figure 24

(b)(6)

(b)(6)

(b)(6)



Figure 25
Auditorium, construction detail,
lobby entrance.

Figure 26
Mr. Dulles's "campus." (SE corner
of building in background.)





Figure 27
Main entrance, construction detail.



Figure 28
Canopy, main entrance, construction
detail.



Figure 29
Cafeteria, arches and windows.



Figure 30
Cafeteria, windows and arches.





Figure 31
Cafeteria, arches and reflections.



(b)(6)

Figure 32
South cafeteria, arches over
entrance.



Figure 33
North Cafeteria, interior detail.



Figure 34
Cafeteria, side view.




Figure 35
Courtyard, Headquarters Building.



Figure 36
Lobby and CIA Seal, main entrance.



Figure 37
Lobby, main entrance.

Figure 38
Corridor on courtyard, first floor.





Figure 39
Leased property: (1) Chamber of
Commerce Building and (2) 1000
Glebe Road, Arlington, Virginia.



Figure 40
Leased property: (1) Key Building
and (2) Ames Building, Rosslyn, Va.



Figure 41
"Assigned" property, the National
Photographic Interpretation Center
(NPIC), Building 213, Washington
Naval Yard.